

OFFICE OF THE SUB DIVISIONAL OFFICER, P.W.D.
SUB DIVISION, WAIDHAN, SINGRAULI M. P.

BUILDING FITNESS CERTIFICATE

(To be filled by the Inspecting Officer)

Name of the Officer : Tejaswani Shukla
Name of the School : E-COAL INTERNATIONAL SCHOOL
Location with name of Education District Sub District : Tehsil – Waidhan, Distt. Singrauli, M.P., 486886
Classification of Building : 14654.10 sq.ft. (Ground Floor)
: 13050.44 sq.ft. (First Floor)

Total Area : 27704.54 sq.ft.
Period for which the certificate is issued : 2022-25

Nature of defects, if any:-

(a) Foundation	: Framed Structure
(b) Superstructure	: Brick Masonry
(c) Doors and Windows	: St ^r . Steel window, Flush door
(d) Wood works	: Door
(e) Roof	: R.C.C
(f) Flooring	: I.T. Floor
(g) Miscellaneous (cracks etc.)	: Not Applicable

Any major defects noticed which will render the building unsafe in any manner : No

Whether maintenance works have been done properly : Yes

Whether the structure is sound or not for conduction classes: **Building is sound and safe**

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building of E-Coal International School, Waidhan, was inspected by me on 07/05/2022 and found to be fit to conduct classes for the reasons stated above.

Place: Waidhan

Date: 07/05/2022

No. 82

Shukla
Sub Divisional Officer
P.W.D. Sub Division Waidhan
Distt.-Singrauli (M.P.)